

# CFMOTO 800MT SPORT and TOURING Safety Recall – Horn wiring harness inspection and adjustment

**DATE:** 19 June 2024

**Recall ID:** REC-005992

**Campaign number:** CF240000003R

## **Make**

CFMOTO

## **Model**

800MT

## **Variants**

800MT SPORT, 800MT TOURING

## **Year range**

2021-2022

## **Affected units**

233

## **What are the defects?**

Due to improper routing during assembly, the wiring harness leading to the vehicle's horn may become damaged or disconnected. As a result, when the steering is operated at its limits the horn may not function afterwards.

## **What are the hazards?**

If the horn does not operate as intended, this could increase the risk of an accident causing serious injury or death to the rider and other road users.

## **What should consumers do?**

Owners of affected motorcycles will be contacted in writing by Mojo Motorcycles. Owners can also contact their nearest authorised CFMOTO service centre, to have the wiring harness inspected and adjusted, free of charge.

**FIND A DEALER:** <https://www.cfmoto.com.au/dealers-on-road>

**Supplier:** Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

**LINK:** <https://www.vehiclerecalls.gov.au/recalls/rec-005992>