

CFMOTO 800MT TOURING Safety Recall – RIGHT HAND SIDE ENGINE SUPPORT

DATE: 15 February 2024

Recall ID: REC-005901

Campaign number: CF240000001R

Make

CFMOTO

Model

800MT TOURING

Variants

800MT TOURING

Year range

2023

Affected units

28

What are the defects?

The engine support mounting bolts may not have been tightened to the correct torque potentially causing them to become loose and detach. If this occurs, the bolt will obstruct the rear foot brake pedal and result in reduced braking performance.

What are the hazards?

A reduction in braking performance could increase the risk of an accident causing injury or death to the rider and/or passenger, or other road users.

What should consumers do?

Owners will be contacted in writing by Mojo Motorcycles. Owners can also contact their nearest CFMOTO service centre to confirm the bolt is at the correct torque specification, free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-on-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.vehiclerecalls.gov.au/recalls/rec-005901>