

CFMOTO 700 CL-X SPORT Safety Recall – ABS Control Module Software Update

DATE: 11 December 2023

Recall ID: REC- 005850

Campaign number: CF230000002R

Make

CFMOTO

Model

700 CL-X

Variants

700 CL-X SPORT

Year range

2021-2022

Affected units

185

What are the defects?

Due to a software issue, the Anti-lock Braking System (ABS) control module may not operate as intended. This may result in a delay in braking performance and/or an increased effort may be required to achieve the expected stopping distance.

What are the hazards?

If the braking system does not operate as intended, it could increase the risk of an accident resulting in serious injury or death to the rider and/or passenger and other road users.

What should consumers do?

Owners of affected motorcycles will be contacted in writing by Mojo Motorcycles. Owners can also contact their preferred Authorised CFMOTO Service Centre, to arrange for the ABS software to be updated, free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-on-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.vehiclerecalls.gov.au/recalls/rec-005850>