

CFMOTO 650MT and 650GT Safety Recall – Gear shift shaft replacement

DATE: 1 July 2024

Recall ID: REC- 006018

Campaign number: CF240000004R

Make

CFMOTO

Model

650MT, 650GT

Variants

650MT, 650GT

Year range

2021

Affected units

16

What are the defects?

Due to a manufacturing defect, the gear shift shaft may have been incorrectly welded. As a result, the rider may be unable to change gears leading to a loss of motive power whilst riding.

What are the hazards?

Inability to change gears and a loss of motive power whilst riding could increase the risk of an accident and injury or death to rider(s) and other road users.

What should consumers do?

Owners of affected motorcycles will be contacted by Mojo Motorcycles. Owners can also contact their nearest authorised CFMOTO service centre to have the gear shift shaft replaced, free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-on-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.vehiclerecalls.gov.au/recalls/rec-006018>