

# CFMOTO U10 PRO – U10 PRO HIGHLAND THROTTLE PEDAL ASSEMBLY REPLACEMENT

DATE: 18 December 2024

**Make**

CFMOTO

**Model**

UFORCE U10 PRO

**Variants**

UFORCE U10 PRO, UFORCE U10 PRO HIGHLAND

**Year range**

2025

**Affected units**

180

**What are the defects?**

The throttle assembly may not fully return to the idle position when released.

**What are the hazards?**

Risk of serious injury or death if the rider is unable to stop the vehicle due to the throttle not returning to idle.

**What should consumers do?**

Consumers should contact their local CFMOTO dealership to arrange inspection and repair of their vehicle.

**FIND A DEALER:** <https://www.cfmoto.com.au/dealers-off-road>

**Supplier:** Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

**LINK:** <https://www.productsafety.gov.au/search-consumer-product-recalls/cfmoto-u10-pro-and-u10-pro-highland-my25-utility-terrain-vehicles>