

CFMOTO 700 CLX HERITAGE – Fuel Tank Inspection

DATE: 27 February 2024

Recall ID: REC- 005907

Campaign number: CF240000002R

Make

CFMOTO

Model

700 CL-X

Variants

700 CL-X HERITAGE

Year range

2021

Affected units

7

What are the defects?

Due to a manufacturing defect, the fuel tank may have been incorrectly welded. This could cause a fuel leak and result in a vehicle fire.

What are the hazards?

A vehicle fire may increase the risk of serious injury or death to the rider, other road users, bystanders, and/or damage to property.

What should consumers do?

Owners of affected motorcycles will be contacted by Mojo Motorcycles. Owners can also contact their nearest authorised CFMOTO service centre to have the fuel tank inspected, if required, and replaced, free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-on-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.vehicle recalls.gov.au/recalls/rec-005907>