

CFMOTO ZFORCE 1000 Safety Recall – Fuel Rail

DATE: 23 December 2020

Make

CFMOTO

Model

ZFORCE 1000

Variants

ZFORCE 1000 SPORT

Year range

2020

Affected units

51

What are the defects?

Fuel may leak from the fuel rail.

What are the hazards?

If fuel were to leak onto the hot engine, the fuel could ignite causing a fire. This can increase the risk of serious injury or death to vehicle occupants.

What should consumers do?

Consumers should contact their local CFMOTO dealership to arrange inspection and repair of their vehicle.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-off-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.productsafety.gov.au/recalls/cfmoto-zforce-1000-sport-side-by-side-vehicles-my2020-0>