

# CFMOTO ZFORCE 1000 Safety Recall – Accelerator Pedal

DATE: 22 December 2020

**Make**

CFMOTO

**Model**

ZFORCE 1000

**Variants**

ZFORCE 1000 SPORT

**Year range**

2020

**Affected units**

111

**What are the defects?**

The accelerator pedal may not return to the idle position as quickly as expected.

**What are the hazards?**

The vehicle may not slow down as quickly as expected. This could increase the risk of an accident and injury to vehicle occupants. In the event of a serious accident this may result in death.

**What should consumers do?**

Consumers should contact their local CFMOTO dealership to arrange inspection and repair of their vehicle.

**FIND A DEALER:** <https://www.cfmoto.com.au/dealers-off-road>

**Supplier:** Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

**LINK:** <https://www.productsafety.gov.au/recalls/cfmoto-zforce-1000-sport-side-by-side-vehicles-my2020>