

CFMOTO U10 PRO – U10 PRO HIGHLAND THROTTLE PEDAL ASSEMBLY REPLACEMENT

DATE: 7 March 2025

Make

CFMOTO

Model

UFORCE U10 PRO HIGHLAND

Variants

UFORCE U10 PRO HIGHLAND XL

Year range

2025

What are the defects?

Cabin doors may unlatch and open without warning due to design defect.

What are the hazards?

Risk of serious injury or death if the door unlatches and opens while vehicle is in use.

What should consumers do?

Stop using the vehicle immediately. Contact their local CFMOTO dealership to arrange inspection and repair of their vehicle free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-off-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.productsafety.gov.au/search-consumer-product-recalls/cfmoto-u10-pro-highland-cfmoto-u10-pro-highland-xl-utvs>