

CFMOTO CFORCE 110 YOUTH ATV Safety Recall – Throttle Limiting Adjustment Screw

DATE: 12 July 2024 (13 August 2024 Updated)

Make

CFMOTO

Model

CFORCE 110

Variants

CFORCE 110

Year range

2023

Affected units

64

What are the defects?

The throttle limiting adjustment screw may be improperly adjusted, which may cause the throttle to become stuck open and cause the vehicle to accelerate without throttle input.

What are the hazards?

There is a risk of serious injury or death if the rider loses control of the vehicle or is unable to stop the vehicle due to a jammed throttle.

What should consumers do?

Consumers should contact their local CFMOTO dealership to arrange inspection and repair of their vehicle.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-off-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.productsafety.gov.au/search-consumer-product-recalls/cfmoto-cf110ay-youth-atv-updated>

