

CFMOTO 150NK, 250NK, 300NK, 300SR Safety Recall – Lower Clamp

DATE: 15 April 2025

Recall ID: REC- 006529

Campaign number: CF2026-001R

Make

CFMOTO

Models

150NK, 250NK, 300NK & 300SR

Variants

All variants within this model

Year range

2019-2020

Affected units

189

What are the defects?

Due to a manufacturing defect, the lower clamp connecting the front suspension to the steering may fracture. This could lead to a loss of vehicle control whilst riding.

What are the hazards?

A loss of vehicle control whilst riding could increase the risk of an accident causing injury or death to rider, passenger and/or other road users.

What should consumers do?

Owners of affected vehicles should contact their nearest authorised CFMOTO service centre to have the lower triple clamp replaced, free of charge.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-on-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.vehiclecalls.gov.au/recalls/rec-006335>