

CFMOTO CFORCE 850 TOURING, CFORCE 1000 TOURING Safety Recall – Throttle Assembly

DATE: 8 November 2024

Make

CFMOTO

Model

CFORCE 850, CFORCE 1000

Variants

CFORCE 850 TOURING, CFORCE 1000 TOURING

Year range

2024

Affected units

92

What are the defects?

The throttle assembly may not fully return to the idle position when released.

What are the hazards?

Risk of serious injury or death if the rider is unable to stop the vehicle due to the throttle not returning to idle.

What should consumers do?

Consumers should contact their local CFMOTO dealership to arrange inspection and repair of their vehicle.

FIND A DEALER: <https://www.cfmoto.com.au/dealers-off-road>

Supplier: Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

LINK: <https://www.productsafety.gov.au/search-consumer-product-recalls/cfmoto-cforce-850-1000-touring-atv>