

# CFMOTO 700MT Safety Recall – Rear Tyre

**DATE:** 13 January 2026

**Recall ID:** REC- 006529

**Campaign number:** CF2026-001R

## **Make**

CFMOTO

## **Model**

700MT

## **Variants**

700MT

## **Year range**

2023-2024

## **Affected units**

6

## **What are the defects?**

Due to a manufacturing defect, the rear tyre steel belt may become damaged under certain off-road conditions or riding extended periods with low tyre pressure. This can lead to a loss of air pressure and result in a loss of vehicle control.

## **What are the hazards?**

A loss of air pressure may result in loss of vehicle control increasing the risk of an accident, causing injury or death to the rider and/or passenger and other road users.

## **What should consumers do?**

Owners of affected vehicles should stop riding immediately and contact their nearest authorised CFMOTO dealer to make an appointment to have the tyre replaced, free of charge. All vehicle owners will be notified in writing.

**FIND A DEALER:** <https://www.cfmoto.com.au/dealers-on-road>

**Supplier:** Mojo Motorcycles PTY LTD the distributor of CFMOTO Australia

**LINK:** <https://www.vehiclecalls.gov.au/recalls/rec-006529>

